HEALTHCARE
Imaging >
Global Support Operations

Field Service Bulletin No. 1

Order No.: DD+DIS042.02E

1 piece UVDY3 MA1

ADC Compact Plus

Type 5146 / 100/200

Rating			When?		
safety relevant	reliability	new function	immediately	next service	as required
	X				**X**

Please file this document in section 10 of your technical documentation

Software ACP_1010 available now

1 General

1.1 Order number

CM+9.5146.1050.2

1.2 Scope of delivery

1 x Hard disk formatter floppy disk
2 x Portex installer floppy disks
3 x Application floppy disks
1 x Empty floppy

2 What is new in ACP_1010?

- Erasure Unit lamps lifetime control algorithm.
  User information text is displayed when it is time to change erasure lamps, always after startup and every 24 hours.
- Stretched acceleration of belt drive input buffer for smoother start of cassette transport to RF-Tag read position.
- Text extension to infocounter identifier for polygon jitter.
- Start cooling of erasure unit with fan again at begin of erase cycle.
- Removed error code 22D55 with ‘COOLING DELAY‘ display. As consequence no more red blinking status display.

printed in Germany 03 / 2002

AGFA